

RealtyCenter.com

Each office independently owned and operated

http://www.state.tn.us/commerce/boards/trec/index.shtml.

DD ODEDTIL ADDRESS

11

Downtown (423) 643-9300 East Brainerd (423) 899-5943 Hixson (423) 842-8887 North Georgia (706) 866-4140 Signal Mtn (423) 886-2601

TENNESSEE RESIDENTIAL PROPERTY CONDITION DISCLOSURE

1	PROPERTY ADDRESS	7942 Hamilton Mill Dr.	CTTYChattanooga
2	SELLER'S NAME(S)	Gary T. Robb & Cheryl A. Robb	PROPERTY AGE 1945
3	DATE SELLER ACQUIRED	THE PROPERTY 1997- DO YOU	OCCUPY THE PROPERTY? <u>VeS</u>
4	IF NOT OWNER-OCCUPIE	D, HOW LONG HAS IT BEEN SINCE THE SELLE	R OCCUPIED THE PROPERTY?
5	(Check the one that applies)	The property is a 💢 site-built home 🗆	non-site-built home
6 7		Property Disclosure Act requires sellers of residentian ne of the following: (1) a residential property disclose	
8		er statement (permitted only where the buyer waives	
9	transfers may be exempt fro	m this requirement (see Tenn. Code Ann. § 66-5-20	09). The following is a summary of the
10	buyers' and sellers' rights	and obligations under the Act. A complete	copy of the Act may be found at

- Sellers must disclose all known material defects and must answer the questions on the Disclosure form in good faith to the best of the seller's knowledge as of the Disclosure date.
- Sellers must give the buyers the Disclosure form before the acceptance of a purchase contract.
- Sellers must inform the buyers, at or before closing, of any inaccuracies or material changes in the condition that have occurred since the time of the initial Disclosure, or certify that there are no changes.
- Sellers may give the buyers a report or opinion prepared by a professional inspector or other expert(s) or certain information provided by a public agency, in lieu of responding to some or all of the questions on the form (See Tenn. Code Ann. § 66-5-204).
- Sellers are not required to have a home inspection or other investigation in order to complete the Disclosure form.
- Sellers are not required to repair any items listed on the Disclosure form or on any past or future inspection report unless
 agreed to in the purchase contract.
- Sellers involved in the first sale of a dwelling must disclose the amount of any impact fees or adequate facility taxes
 paid.
- Sellers are not required to disclose if any occupant was HIV-positive, or had any other disease not likely to be transmitted by occupying a home, or whether the home had been the site of a homicide, suicide or felony, or act or occurrence which had no effect on the physical structure of the property.
- Sellers may provide an "as is", "no representations or warranties" disclaimer statement in lieu of the Disclosure form only if the buyer waives the right to the required disclosure, otherwise the sellers must provide the completed Disclosure form (See Tenn. Code Ann. § 66-5-202).
- 10. Sellers may be exempt from having to complete the Disclosure form in certain limited circumstances (e.g. public auctions, court orders, some foreclosures and bankruptcies, new construction with written warranty or owner has not resided on the property at any time within the prior 3 years. See Tenn. Code Ann. § 66-5-209).
- Buyers are advised to include home and wood infestation, well, water sources, septic system, lead-based paint, radon,
 mold, and other appropriate inspection contingencies in the contract, as the Disclosure form is not a warranty of any kind
 by the seller, and is not a substitute for any warranties or inspections the buyer may desire to purchase.
- 12. Any repair of disclosed defects must be negotiated and addressed in the Purchase and Sale Agreement; otherwise, seller
 is not required to repair any such items.
- 39 13. Buyers may, but do not have to, waive their right to receive the Disclosure form from the sellers if the sellers provide a disclaimer statement with no representations or warranties (see Tenn. Code Ann. § 66-5-202).

- 14. Remedies for misrepresentations or nondisclosure in a Property Condition Disclosure statement may be available to buyer and are set out fully in Tenn. Code Ann. § 66-5-208. Buyer should consult with an attorney regarding any such matters.
- 44 15. Representations in the Disclosure form are those of the sellers only, and not of any real estate licensee, although licensees are required to disclose to all parties adverse facts of which the licensee has actual knowledge or notice.
 - 16. Pursuant to Tenn. Code Ann. § 47-18-104(b), sellers of newly constructed residences on a septic system are prohibited from knowingly advertising or marketing a home as having more bedrooms than are permitted by the subsurface sewage disposal system permit.
 - 17. Sellers must disclose the presence of any known exterior injection well, the results of any known percolation test or soil absorption rate performed on the property that is determined or accepted by the Department of Environment and Conservation, and whether the property is located within a Planned Unit Development as defined by Tenn. Code Ann. § 66-5-213 and, if requested, provide buyers with a copy of the development's restrictive covenants, homeowner bylaws and master deed. Sellers must also disclose if they have knowledge that the residence has ever been moved from an existing foundation to another foundation.

The Buyers and Sellers involved in the current or prospective real estate transaction for the property listed above acknowledge that they were informed of their rights and obligations regarding Residential Property Disclosures, and that this information was provided by the real estate licensee(s) prior to the completion or reviewing of a Tennessee Residential Property Condition Disclosure, a Tennessee Residential Property Condition Disclosure, a Tennessee Residential Property Condition Exemption Notification. Buyers and Sellers also acknowledge that they were advised to seek the advice of an attorney on any legal questions they may have regarding this information or prior to taking any legal actions.

The Tennessee Residential Property Disclosure Act states that anyone transferring title to residential real property must provide information about the condition of the property. This completed form constitutes that disclosure by the Seller. The information contained in the disclosure is the representation of the owner and not the representation of the real estate licensee or sales person, if any. This is not a warranty or a substitute for any professional inspections or warranties that the purchasers may wish to obtain.

Buyers and Sellers should be aware that any sales agreement executed between the parties will supersede this form as to the terms of sale, property included in the sale and any obligations on the part of the seller to repair items identified below and/or the obligation of the buyer to accept such items "as is."

INSTRUCTIONS TO THE SELLER

Complete this form yourself and answer each question to the best of your knowledge. If an answer is an estimate, clearly label it as such. The Seller hereby authorizes any agent(s) representing any party in this transaction to provide a copy of this statement to any person or entity in connection with any actual or anticipated sale of the subject property.

73 THE SUBJECT PROPERTY INCLUDES THE ITEMS CHECKED BELOW: Garage Door Opener(s) (Number of openers) 74 Wall/Window Air Conditioning 75 Ice Maker Hookup Window Screens Garage Door Remote(s) 76 Fireplace(s) (Number) Intercom 77 Microwave Gas Starter for Fireplace TV Antenna/Satellite Dish (excluding components) Garbage Disposal Gas Fireplace Logs 78 Central Vacuum System and attachments Smoke Detector/Fire Alarm 79 Trash Compactor Spa/Whirlpool Tub Patio/Decking/Gazebo 80 Water Softener Hot Tub 220 Volt Wiring Installed Outdoor Cooking Grill Washer/Dryer Hookups 81 Sauna 82 Irrigation System Pool □ In-ground □ Above-ground Dishwasher A key to all exterior doors Access to Public Streets 83 All Landscaping and all outdoor lighting Sump Pump Rain Gutters 84 85 Burglar Alarm/Security System Components and controls 86 Current Termite contract with

46

47

48

49

50 51

52

53

54

55

56

57

58 59

60

61

62

63 64

65

66

67

68

69 70

71

72

87	☐ Heat Pump Unit #1	<u> </u>	A	ge (A	pprox)								
88	☐ Heat Pump Unit #2		A	ge (A	pprox)								
89	□ Heat Pump Unit #3	***	A	ge (A	pprox)								
90	★ Central Heating Unit #	1	_17	Ag	e X	Electric		Gas	s 🗆	Ot	her		
91	Central Heating Unit #	2611	17	¬_ Ag	100	Electric		Gas	s 🗆	Ot	her		
92	☐ Central Heating Unit #.	3		Ag	e 🗆	Electric		Gas	s 🗆	Ot	her		
93	Central Air Conditionin	ng #1	_17	Ag	e #	Electric		Gas	s 🗆	Ot	her		
94	Central Air Conditionin	ng #2	_17	Ag	e 🏚	Electric		Gas	s 🗆	Ot	her		
95	□ Central Air Conditionin	ng #3		Ag	e 🗆	Electric	С	Gas	s 🗆	Ot	her		
96	₩ Water Heater #1	17	_ Age		Electric	#	Gas		Solar		Other		
97	□ Water Heater #2		Age		Electric		Gas		Solar		Other	·	
98	□ Other							other _					
99	Garage Attac	hed 🗆	Not Att	ached		Carport							
100	Water Supply City		Well			Private	J 🗆	Itility	□ O	ther_			
101	Gas Supply 👉 Utilit	у 🗆	Bottled			Other							
102	Waste Disposal + City	Sewer 🗆	Septic 7	Γank		Other _				,			
103	Roof(s): Type Shin	19/25				Ago	e (appr	ox):	16	7			
104 105	Other Items:												
106 107													
	To the best of your knowled	lge, are any	of the ab	ove N	OT in o	perating	condit	ion?		YE	ES	 NO	
107	To the best of your knowled If YES, then describe (attac					perating	condit	ion?		YF	ES	≯ NO	
107 108 109 110 111 112 113 114	STEELE LEGENDARDON SELVENDON SELVEND	h additional	sheets if	fneces	ssary):								
107 108 109 110 111 112 113 114 115 116 117 118	If YES, then describe (attac	h additional	sheets if	f neces	ssary): perty are	e (e.g. sec	curity s						
107 108 109 110 111 112 113 114 115 116 117 118 119 120	If YES, then describe (attack) Leased Items: Leased item	h additional	sheets if	f neces	essary): perty are	e (e.g. sec pay balan	curity s	system	s, water	softe	ner sys	tems, etc.):	
107 108 109 110 111 112 113 114 115 116 117 118 119 120	If YES, then describe (attack) Leased Items: Leased item If leases are not assumable, B. ARE YOU (SELLER)	h additional	sheets if	f neces	essary): perty are	e (e.g. sec pay balan	curity s	system:	s, water N ANY Y	softe OF T	ner sys	tems, etc.): OLLOWING?	
107 108 109 110 111 112 113 114 115 116 117 118 119 120 121	If YES, then describe (attace Leased Items: Leased item If leases are not assumable, B. ARE YOU (SELLER) All above YES	it will be So	in with the	f neces	essary): perty are	pay balan	nce.	system:	s, water	softe OF T	ner sys	tems, etc.): OLLOWING? UNKNOWN	
107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122	If YES, then describe (attack Leased Items: Leased item If leases are not assumable, B. ARE YOU (SELLER) All above YES Interior Walls	it will be So	in with the	f neces	essary): perty are	pay balan	nce. NCTIO	system:	s, water	softe	ner sys	tems, etc.): OLLOWING? UNKNOWN	
107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123	Leased Items: Leased item If leases are not assumable, B. ARE YOU (SELLER) A Bove YES Interior Walls Ceilings 5	it will be So	in with the	f neces	essary): perty are	pay balan ALFUN Roof Co Basemen	nce. NCTIO	system:	N ANY	of T	ner sys	tems, etc.): DLLOWING? UNKNOWN	
107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124	Leased Items: Leased item If leases are not assumable, B. ARE YOU (SELLER) A Bove YES Interior Walls Ceilings Seem	it will be So	in with the	f neces	essary): perty are	pay balan IALFUN Roof Co Basemer Foundati	nce. NCTIO ompone nt ion	system:	s, water	of T	ner sys	tems, etc.): OLLOWING? UNKNOWN	
107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125	Leased Items: Leased item If leases are not assumable, B. ARE YOU (SELLER) Above YES Interior Walls Ceilings Seen Windows Replaced	it will be So	in with the	f neces	essary): perty are	pay balan ALFUN Roof Co Basemen Foundati	nce. NCTIO	system:	s, water	softe	ner sys	tems, etc.): OLLOWING? UNKNOWN	

			YES	NO	UNKNOWN			YES	NO	UNKNOWN
129	Sev	ver/Septic		×		Heat Pump			X	
130	Ele	ctrical System		+		Central Air Condit	ioning	X		
131 132		erior Walls	×			Double Paned or In Window and/or Do		l 🗆	X	
133 134	If a	ny of the above i	s/are mai	rked YES	s, please explain: UNITS hav	e Needed Fred	m		- 17 E-1410	
135 136	Ple	ase describe any	repairs n	ade by y	ou or any previous	owners of which you are	e aware			
137	٠.					E FOLLOWING:	YES	NO	UN	KNOWN
138 139 140 141 142	1.	such as, but not or chemical stor	limited t	o: asbes s, methar	tos, radon gas, lead nphetamine, contar ast mold presence	minated soil or		7	-	
143 144 145	2.		ences, an	d/or driv		ers, such as walls, but ghts and obligations	*			
146 147	3.	Any authorized property, or con			drainage or utilitie perty?	s affecting the		A		
148 149 150	4.				t survey of the propy: (check here is			¥	-	
151 152	5.	Any encroachm ownership intere			or similar items that ?	may affect your		A	-	
153 154	6.	Room additions repairs made wi			cations or other alt ermits?	erations or		Val-		
155 156	7.	Room additions repairs not in co			cations or other alt ilding codes?	erations or		*	-8	
157 158	8.	Landfill (compa thereof?	icted or o	therwise	on the property or	any portion		#		
159	9.	Any settling fro	m any ca	use, or sl	ippage, sliding or o	other soil problems?		+	-	
160	10.	Flooding, draina	age or gra	ading pro	blems?			¥		
161	11.	Any requirement	t that flo	od insura	nce be maintained	on the property?		1	_	
162	12.	Is any of the pro	perty in	a flood p	lain?			*		
163 164 165 166 167 168 169	13.	standing water v If yes, please ex	within for plain. If	undation necessar	intrusions(s) from and/or basement? y, please attach an aining to these repa	additional sheet		×		
170 171 172 173 174 175	14.	tremors, wind, s	torm or v	wood des	m fire, earthquake, troying organisms? e sheet if necessary			A	-	
176		If yes, has said o	damage h	een rena	ired?			П		п

				YES	NO	UNKNOWN	
177 178	15.	Any zoning violations, nonconforming uses and/or violations "setback" requirements?	of		*		
179	16.	Neighborhood noise problems or other nuisances?			1		
180	17.	Subdivision and/or deed restrictions or obligations?		1			
181 182	18.	A Condominium/Homeowners Association (HOA) which has over the subject property?		*			
183 184 185 186 187		Name of HOA: Ham, Iton Mill Home owners HOA Phone Number: Special Assessments: Management Company: Management Co. Address: W/A	Monthly Dues: Transfer Fees: Phone:				/yeav
188 189	19.	Any "common area" (facilities such as, but not limited to, poc courts, walkways or other areas co-owned in undivided intere			1		
190	20.	Any notices of abatement or citations against the property?			4		
191 192	21.	Any lawsuit(s) or proposed lawsuit(s) by or against the seller or will affect the property?	which affects		×		
193 194 195 196 197	22.	Is any system, equipment or part of the property being leased' If yes, please explain, and include a written statement regardin information.			*		
198 199	23.	Any exterior wall covering of the structure(s) covered with exinsulation and finish systems (EIFS), also known as "synthetic			4		
200 201 202 203 204 205 206 207		If yes, has there been a recent inspection to determine whethe has excessive moisture accumulation and/or moisture related (The Tennessee Real Estate Commission urges any buyer or s professional inspect the structure in question for the preceding professional's finding.) If yes, please explain. If necessary, please attach an additional	damage? eller who encour g concern and pr				
208 209 210 211 212	24.	Is heating and air conditioning supplied to all finished rooms? If the same type of system is not used for all finished rooms, p		*			
213 214 215 216	25.	If septic tank or other private disposal system is marked under it have adequate capacity and approved design to comply with and local requirements for the actual land area and number of facilities existing at the residence?	present state			×	
217 218	26.	Is the property affected by governmental regulations or restrict approval for changes, use, or alterations to the property?	tions requiring	#			
219 220 221	27.	Is this property in a historical district or has it been declared hany governmental authority such that permission must be obtacertain types of improvements or aesthetic changes to the property.	ined before		#		
222	28.	Does this property have an exterior injection well located any	where on it?		A		
223 224 225 226	29.	Is seller aware of any percolation tests or soil absorption rates performed on the property that are determined or accepted by the Tennessee Department of Environment and Conservation? If yes, results of test(s) and/or rate(s) are attached.			#		



			YES	NO	UNKNOWN
227 228	30.	Has any residence on this property ever been moved from its original foundation to another foundation?		$\not\leftarrow$	
229 230 231 232 233 234 235 236 237	31.	Is this property in a Planned Unit Development? Planned Unit Development is defined pursuant to Tenn. Code Ann. § 66-5-213 as "an area of land, controlled by one (1) or more landowners, to be developed under unified control or unified plan of development for a number of dwelling units, commercial, educational, recreational or industrial uses, or any combination of the foregoing, the plan for which does not correspond in lot size, bulk or type of use, density, lot coverage, open space, or other restrictions to the existing land use regulations." Unknown is not a permissible answer under the statute.	*		
238 239 240 241 242 243 244	D.	CERTIFICATION. I/We certify that the information herein, concerning the 7942 Hamilton Mill Dr., Chattanooga, TN 37421 is true and correct to the best of my/our knowledge as of the date signed. She conveyance of title to this property, these changes will be disclosed in an add Transferor (Seller) Gary T. Robb Transferor (Seller) Cheryl A. Robb	ould any	of these o	conditions change prior to
245 246 247 248		Parties may wish to obtain professional advice and/or inspections of appropriate provisions in the purchase agreement regarding advi			
249 250 251	insp	nnsferce/Buyer's Acknowledgment: I/We understand that this disclosure state section, and that I/we have a responsibility to pay diligent attention to and inquedent by careful observation. I/We acknowledge receipt of a copy of this disc	ire abou		
252		Transferee (Buyer)	Date		Time

If the property being purchased is a condominium, the transferee/buyer is hereby given notice that the transferee/buyer is entitled, upon request, to receive certain information regarding the administration of the condominium from the developer or the condominium association as applicable, pursuant to Tennessee Code Annotated §66-27-502.

NOTE: This form is provided by TAR to its members for their use in real estate transactions and is to be used as is. This form contains language that is in addition to the language mandated by the state of Tennessee pursuant to the disclosure requirements of the "Tennessee Residential Property Disclosure Act". Tennessee Code Annotated § 66-5-201, et seq. By downloading and/or using this form, you agree and covenant not to alter, amend, or edit said form or its contents except as where provided in the blank fields, and agree and acknowledge that any such alteration, amendment or edit of said form is done at your own risk. Use of the TAR logo in conjunction with any form other than standardized forms created by TAR is strictly prohibited. This form is subject to periodic revision and it is the responsibility of the member to use the most recent available form.



253

254

255

256

Transferee (Buyer) ___

Time ___



PREPARED FOR:

MR. CHRIS KARACALIDIS

GRANGE MUTUAL CASUALTY INSURANCE COMPANY

4000 RUSSELL PARKWAY

WARNER ROBINS, GEORGIA 31088

CHERYL AND GARY ROBB

7942 HAMILTON MILL DRIVE CHATTANOOGA, TENNESSEE 37421-2761 CLAIM NUMBER: HP0001483425

DONAN PROJECT NUMBER: 12-12080810-0

PREPARED BY:

DONAN ENGINEERING CO., INC.

500 C Ambrose Avenue NW Knoxville, Tennessee 37921 865-688-7220

AUGUST 30, 2012

MATTHEW G. RICHARDSON, P.E. SENIOR FORENSIC ENGINEER

John G. Donan, Jr., P.E. Chairman of the Board

J. Lyle Donan, P.E. President



CORRESPOND TO: 500 C Ambrose Avenue NW Knoxville, Tennessee 37921 865-688-7220 865-688-7276 fax

August 30, 2012

Mr. Chris Karacalidis **Grange Mutual Casualty Insurance Company** 4000 Russell Parkway Warner Robins, Georgia 31088

RE: Cheryl and Gary Robb

7942 Hamilton Mill Drive

Chattanooga, Tennessee 37421-2761 Claim Number: HP0001483425

Donan Project Number: 12-12080810-0

Dear Mr. Karacalidis:

At your request, on August 20, 2012, a study was made on the house at the above-referenced address. The purpose of the study was to determine if hail damaged the roof shingles, and to determine the cause of the water stain. Mrs. Robb was present to point out areas of concern and to provide firsthand information. This letter, with the attached photographs and EagleView document, is the report of my findings and conclusions.

Description of Property

For purposes of this report, the house is considered to face north toward Hamilton Mill Drive. The house is a one and one-half-story, wood-framed structure over a basement (Photographs 1 and 2). The exterior walls are covered with a combination of brick veneer and hardboard siding, and the roof is clad with three-tab, fiberglass-mat asphalt shingles. According to Mrs. Robb, the house was built in 1992, and the family has lived there since 1994. Aerial photographs and a roof layout diagram, with dimensions and slope references, can be found in the EagleView report attached as Appendix A.



P.O. Box 182758 Columbus, Ohio 43218-2758 478.971.2000 or 1.800.342.3785 FAX 1.800.342.8089 grangeinsurance.com

September 04, 2012

Cheryl Robb 7942 Hamilton Mill Dr Chattanooga, TN 37421-2761

RE:

Insured:

Cheryl Robb

Claim:

HP0001483425

Date of Loss:

03/02/2012

Karacalidis ?

Dear Cheryl Robb:

This letter follows our conversation regarding the above claim. As discussed, the engineer's inspection found no storm damage to the roof. I have enclosed a copy of their report for your review. Based on these findings and the interior stain repairs not exceeding your policy deductible we have closed our file without payment.

Your homeowner's policy allows one year from the date of loss for your claim to be concluded.

This letter should not be construed as a waiver of any of the terms, requirements and conditions of our insurance contract with you, or as a waiver of any right, claim or potential defense there under, all of which we respectfully reserve without qualification or limitation. If you have any questions or concerns please feel free to contact me at (800) 342-3785 ext. 245.

Sincerely,

Christopher Karacalidis Field Property Manager

Grange Mutual Casualty Insurance Company

Claim Number: HP0001483425

August 30, 2012

Page 3

As would be expected, the softer the material being struck, the more energy it absorbs and the more heavily it may be deformed. The material properties and underlying support of the object being struck have a significant effect on the amount of the hailstone's kinetic energy that is transferred to the object. For example, soft metals that are not backed or bonded to a solid substrate may be easily damaged during a hailstorm, whereas a similar surface, bonded to a solid substrate, may go undamaged. Light-gauge metal surfaces such as vents, gutters, and downspouts are typically the first surfaces to exhibit signs of hail impact. Dents in light-gauge metal surfaces do not prove damage to asphalt shingles, but this information can provide collateral indicators of the characteristics of the hail that fell.

Collateral Indicators of Hail

A survey of the property was conducted in search of collateral indicators of hail. Such surfaces include, but are not limited to, exterior metal appurtenances, exterior wood surfaces, window wraps and screens, HVAC condenser fins, and metal roof appurtenances such as vents and various caps. Collateral indicators of hail are extremely important in any hail study, as they provide clear and tangible clues about the nature of the hailstorm such as the size of hailstones, the direction from which the hailstones originated, and the density or number of hailstones that fell per unit area. Hail impacts have cleaned off the oxidization of the condenser housings on the east side of the house (Photograph 5). On the roof, cosmetic dents were found in the light-gauge caps, and clean spots were found on algae-stained shingles (Photographs 6 through 8).

Many factors should be considered when estimating the size of hail that impacted a property, including the gauge (thickness) of the metal, the angle of impact, the speed of impact, and the hardness of the hailstone. However, laboratory tests allow us to predict the size of hail based on on-site collateral indicators. In general, dents in light-gauge metals, such as the furnace vent caps, can be up to three times larger than the actual hailstone, whereas dents in heavier-gauge metals may be as small as half of the size of the impacting hailstone.

Based on this study of the collateral indicators, hail up to ¾ inch in diameter fell at this site. Most of the hail that fell was ½ inch in diameter and smaller. While larger hail may have impacted this property, no evidence was found in any of the collateral surfaces.



Background

Mrs. Robb reported that on March 2, 2012, severe storms producing hail and strong winds caused widespread property damage throughout Chattanooga, Tennessee and the surrounding area. Tornados are known to have accompanied these storms in some area. Several neighborhood homes have received new roofs.

Interior Observations

Mrs. Robb pointed out a stain to the ceiling in one of the upstairs rooms (Photographs 3 and 4). This room is located on the east end of the house.

Hail Damage Defined

Hail damage to asphalt shingles is defined as an identifiable mark of distress caused by hail that has measurably and significantly reduced the integrity or functionality of the overall shingle, where the shingle was sound prior to the hail impact. Hail damage is sometimes found in the form of a fracture of the shingle's fiberglass mat, identified by a deflection (bruise) through the entire thickness of the shingle. It can also be in the form of a mark of significant granule displacement, causing exposure of the asphalt layer of the shingle, but without mat fracture. In severe cases, the hail may have fractured the shingle mat as well as displaced the granules and asphalt, revealing the shingle's underlying fiberglass mat. Regardless, if hail has exposed a significant area of the shingle below the granulated layer of an otherwise sound shingle, the life of the shingle has been reduced, thereby classifying the shingle as "hail damaged."

General Hail Information

When hail strikes a surface, a transfer of energy takes place between the hailstone and the surface it strikes. Some of the hailstone's original kinetic energy may be dispersed as kinetic energy (a bounce), absorbed by the hailstone itself as "strain" energy (especially in instances when hailstones fracture on impact), or transferred to the impacted object as strain energy. The angle of impact plays a large role in determining the amount of energy that is transferred into the object being struck by the hailstone. When a soft material is impacted by hail, the strain energy may increase within the material to the point that localized, permanent deformation occurs.



Grange Mutual Casualty Insurance Company

Claim Number: HP0001483425

August 30, 2012

Page 4

Controlled laboratory testing has found that hail smaller than 1 inch in diameter lacks sufficient mass to cause a significant loss in functionality or integrity to three-tab, fiberglass-mat asphalt shingles. Hail smaller than 1 inch in diameter can facilitate minor granule loss that is not classified as hail damage because it does not significantly reduce the service life of the impacted shingles.

Study of the Roof Shingles

The roof was studied for evidence of hail damage (Photographs 9 through 12). Shingles with greater susceptibility to hail damage were studied first. Inherently susceptible shingles are those that would have faced the incoming hailstones and those that are less firmly supported from underneath by a rigid roof deck. Shingles that cover ridges, in woven valleys, along edges on a roof, and edges of shingles themselves are inherently more susceptible to hail damage due to the absence of firm backing. This allows an incoming hailstone to fracture the shingle considerably easier than a shingle that is firmly supported. No hail damage was found to any of the shingles on this roof (Photographs 13 and 14).

Evidence of inadvertent man-made damage was found on the shingles of this roof (Photographs 15 through 20). Man-made activities sometimes mar roof shingles and can easily be mistaken for hail. Often the shingles installers will drop or drag equipment or even other shingles across the roof, scarring the shingles. Foot scuffing is also common, particularly along the bottom edge of the shingle tabs. Man-made shingle damage, such as implement gouging, is easily created when the surface of new shingle roofing is hot from sunshine, at which time the shingles become very pliable and impressionable.

Numerous holes were found through the shingles where the roofing contractor installed toe boards (Photographs 21 through 24). Toe boards are required on steeper roof slopes to keep workmen and materials from sliding off. Because roof shingles are installed from the bottom of a roof slope up, toe boards must be secured to the roof deck through the shingles. The holes are generally filled with sealant once the toe boards are removed.

Some areas of this roof are slightly stained by algae growth (Photograph 25). Typically, algae are most common on north-facing roof slopes that do not receive a large amount of direct sunlight, but it can appear on any roof slope. Algae growth is commonly seen on light-colored shingles (dark-colored shingles mask its presence), and it does no harm to the structural integrity of the shingle. To combat this unsightly cosmetic condition, certain types of metal surfaces can



be strategically placed to leach minute particles of the metal on impact with rain, thereby chemically inhibiting algae growth. Washing the shingles with a diluted bleach solution is a common method of algae removal; however, improper cleaning methods may damage the shingles and do more harm than good.

Study of the shingles revealed heat-related distress in the form of heat blisters (Photographs 26 through 30). Shortly after installation, when the asphalt was fresh and volatile organic compounds were still sufficiently contained in the asphalt, these shingles underwent substantial heat buildup that caused the asphalt in the shingle to quickly flash off the volatiles contained in it. As the asphalt heats up, volatile compounds separate from the asphalt mixture and collect as vapor under the granule layer of the shingles, forming small blisters. With continued heating, the blisters continue to grow until the volatiles flash off. As the asphalt weathers and begins to embrittle, the granule covering eventually erodes away. The uncovered blisters are characterized by an open-centered, dome-shaped, or crater-like cavity with a rim resembling a volcano.

Once a heat blister "pops," the asphalt and granules originally covering it are lost, leaving a hole exposing the interior mat of the shingle. In large quantities, this exposure can allow accelerated weathering and premature failure of the shingles. On this roof, the extent of heat blisters on the shingles suggests a probability of excessive temperature in the attic, normally caused by inadequate ventilation.

Heat blisters may be mistaken for hail damage, as both can lead to granule loss in a circular or elliptical geometry. However, close study shows sharp contrasts between hail damage and heat blisters. Hail creates granule loss that is associated with a depression resulting from the impact of hail on the shingle. With time, the depression may disappear, but the hail mark will retain the appearance of an abrasion, with typically ill-defined edges. On the contrary, heat blisters are not depressions but actually raised domes on the surfaces of the shingles. They have sharp and defined edges, and a small test probe can often be inserted into the gap created between the edge of the heat blisters and the underlying shingle mat.

Several "nail pops" and improperly installed nails were found on this roof (Photographs 31 through 36). A nail pop is the outward progression of a nail fastening a shingle to the roof deck. Nail pops can distress and/or puncture an overlying shingle and can be mistaken as hail damage. Nail pops are common on roofs and can occur from various adverse conditions. They are typically a result of poor attic ventilation, which is in turn the culprit for excessive moisture and/or



thermal expansion and contraction of the wood substrate. But nail pops can also be caused by using improperly sized nails, installing the nails through knots in the wood deck sheathing, or installing nails through the edges of adjacent pieces of sheathing. Nails installed at an angle can also result in distress to overlying shingles.

Roofing fasteners were observed to have been improperly installed throughout the roof. Industry practice for conventional three-tab asphalt or dimensional shingles nailed on slopes ranging up to 21/12 pitch calls for four nails to be installed per shingle where no other adverse conditions such as expected high winds apply (Figure 1).




Figure 1: Proper Fastener Installation

All shingles should receive no less than four nails, one at each end and one over each interior cutout (keyway). The nails should be located approximately $5^5/_8$ inches above the bottom of the shingle, above the upper shingle cover and below the self seal strip for three tab shingles or on the nail line provided by the manufacturer for dimensional shingles. Nails installed below this line are exposed on the roof to the elements and become potential leak sources, and nails through the sealant strip or above the sealant strip (or nail line for dimensional shingles) either undermine its adhesive potential or greatly reduce the shingle's overall



fastening to the roof. It is important to note that although one should install four nails per shingle as shown in the preceding figure, if nailed correctly, each shingle is provided a total of eight nails binding it to the roof deck, as the four nails driven through an overlain shingle also penetrate the top of the underlying shingle (if they too are driven properly).

Additional areas of concern were observed on the roof. The sealant and deteriorated trim at the siding/brick interface over the front door could allow minor water intrusion (Photograph 37). The north-facing side of the chimney is unpainted but cannot be seen from the ground (Photograph 38). The raised fasteners on the flue base and the compromised vent stack and boot on the east end of the roof can allow water intrusion (Photographs 39 and 40). These two locations are the most probable source of the water intrusion that is causing the stain in the eastern upstairs room.

In general, the shingles on this roof are in fair condition, except for the observed heat blisters, inadvertent man-made damage, nail pops, and toe board installation damage. The granule loss experienced by these roof shingles has occurred as a result of normal aging.

Granular-surfaced roof shingles constantly shed granules at varying rates throughout their service life. The accumulation of shingle granules found in the gutters and downspouts is typical of a roof in the first one-third or final one-third of its life; however, granule accumulations can occur anytime, particularly if the gutters are not regularly maintained. As granules are shed, they tend to reside on the shingle surface until a heavy rain or even small hail facilitates their progression into the gutters.

During the first few years, granules not firmly embedded into the bitumen matrix are easily lost due to various causes. These lost granules do not affect the aging rate of the roof shingles. However, during the final stage of the shingle's life, many of the volatile components within the bitumen matrix have evaporated, causing the shingle mat to shrink. As this occurs, granules are slowly shed, exposing more of the shingle mat to the sun's radiation. Consequently, shrinkage of the asphalt mat increases, facilitating accelerated granule loss. This process continues until the shingle mat is sufficiently exposed and deteriorated, such that the watertight condition of the roof system is compromised.



Grange Mutual Casualty Insurance Company

Claim Number: HP0001483425

August 30, 2012

Page 8

Summary of Conclusions

In summary, based on what is known at this time, I am of the opinion that:

- Evidence of ¾-inch diameter hail impact was found in the form of cosmetic dents and clean spots.
- Hail smaller than 1 inch in diameter is incapable of damaging sound three-tab, fiberglass-mat asphalt shingles.
- Any hail that has impacted this roof was of insufficient mass and velocity to compromise the integrity and functionality of these shingles.
- No hail damage was found to the shingles on this roof.
- The shingles on this roof have inadvertent man-made blemishes caused by workmen or others, algae growth, heat blisters, nail pops, toe board damage, and improperly-installed nails.
- The water intrusion that is causing the interior stain is originating at the compromised vent stack and boot, and at the compromised fasteners for the flue base.

We appreciate your confidence in our professional services.

Sincerely,

DONAN ENGINEERING CO., INC.

Matthe D. Birlande

Matthew G. Richardson, P.E. Senior Forensic Engineer

Attachments

